



Item	20mm	Description	Potential Problem	Measure	Recommended Inspection, Potential Replacement*	Latest Replacement after
Syste	m Joint					
1	SB1069-L1220	bearing nut	wear	replacing	every 6 months	36 months
3	GS2611-040	sliding washer, Ø = 26mm	wear	replacing	every 6 months	18 months
3	GS2611-045					
3	GS2611-050					
3	GS2611-055					
3	GS2611-060					
4	VE3771-012/26	O-ring damper	wear	replacing	every 6 months	18 months
5a	BP1211-L060	sliding bushing	wear	replacing	every 6 months	18 months
6	SL0265-L/AL	cover plate, left lateral or right medial, aluminium**	wear	replacing	every 6 months	36 months
6	SL0265-R/AL	cover plate, left medial or right lateral, aluminium**				
7a	VE3771-11/15	O-ring for securing the alignment screw**	wear	replacing	every 6 months	18 months
7c	VE3771-04/10	O-ring for securing the motion limiting screw**			every 6 months	18 months
9	PN0006-L02	stop damper**	wear	replacing	every 6 months	18 months
11	SL0285-06	extension stop**	wear	replacing	every 6 months	if required
12	SC1405-L14	countersunk flat head screw with hexalobular socket**	wear	replacing	every 6 months	36 months
13	SC1406-L14	countersunk flat head screw with hexalobular socket (axle screw)**				
6-13	SL2955-L	functional unit plug + go modularity, left lateral or right medial***	loss of function, wear	replacing	every 6 months	36 months
6-13	SL2955-R	functional unit plug + go modularity, left medial or right lateral***				
Sprin	g Units					
14	VE3771-08/10	O-ring for securing the spring unit	wear	replacing	every 6 months	18 months
15	SH5803-15/07	spring unit, blue, normal, max. 15° range of motion	wear radial move of disc springs noise of spring unit with coil spring noise of spring unit with disc springs	replacing realigning disc springs	every 6 months	18 months
15	SH5803-15/15	spring unit, green, medium, max. 15° range of motion		with pliers greasing the coil spring		
15	SH5803-10/21	spring unit, white, strong, max. 10° range of motion				
15	SH5803-10/31	spring unit, yellow, very strong, max. 10° range of motion				
15	SH5803-05/63	spring unit, red, extra strong, max. 5° range of motion		laterally with spray oil (article no.: FT3000-15)		
Syste	m Anchors and S	ystem Side Bars				
16	see catalogue	system anchor and system side bar	wear or breakage	replacing	every 6 months	if required

^{*} depending on the assessment of the distributor of the custom-made product regarding the patient's usage behaviour



^{**} is part of the functional unit

^{***} included system components can be exchanged separately