

Item	14mm	Description	Potential Problem	Measure	Recommended Inspection, Potential Replacement*	Latest Replacement after
Syste	m Joint					
1	SB9669-L0950	bearing nut	wear	replacing	every 6 months	36 months
3	GS1910-040	sliding washer, Ø = 19mm	wear	replacing	every 6 months	18 months
3	GS1910-045					
3	GS1910-050					
3	GS1910-055					
3	GS1910-060					
4	VE3771-010/20	O-ring damper	wear	replacing	every 6 months	18 months
5a	BP1110-L050	sliding bushing	wear	replacing	every 6 months	18 months
6	SL0252-L/AL	cover plate, left lateral or right medial, aluminium**	wear re	replacing	every 6 months	36 months
6	SL0252-R/AL	cover plate, left medial or right lateral, aluminium**				
7a	VE3771-08/15	O-ring for securing the alignment screw**	wear	replacing	every 6 months	18 months
7c	VE3771-04/10	O-ring for securing the motion limiting screw**			every 6 months	18 months
9	PN0004-L02	stop damper**	wear	replacing	every 6 months	18 months
11	SL0282-04	extension stop**	wear	replacing	every 6 months	if required
12	SC1405-L12	countersunk flat head screw with hexalobular socket**	wear	replacing	every 6 months	36 months
13	SC1405-L12	countersunk flat head screw with hexalobular socket (axle screw)**				
6-13	SL2952-L	functional unit plug + go modularity, left lateral or right medial***	loss of function, wear	replacing	every 6 months	36 months
6-13	SL2952-R	functional unit plug + go modularity, left medial or right lateral***				
Spring	g Units					
14	VE3771-06/10	O-ring for securing the spring unit	wear	replacing	every 6 months	18 months
15	SH5801-15/03	spring unit, blue, normal, max. 15° range of motion	wear radial move of disc springs noise of spring unit with coil spring noise of spring unit with disc springs	replacing realigning disc springs	every 6 months	18 months
15	SH5801-15/06	spring unit, green, medium, max. 15° range of motion		with pliers greasing the coil spring with orthosis joint grease or spray oil (article no. FT3000-15) greasing disc springs		
15	SH5801-10/12	spring unit, white, strong, max. 10° range of motion				
15	SH5801-10/19	spring unit, yellow, very strong, max. 10° range of motion				
15	SH5801-05/33	spring unit, red, extra strong, max. 5° range of motion		laterally with spray oil (article no.: FT3000-15)		
Syste	m Anchors and S	ystem Side Bars				
16	see catalogue	system anchor and system side bar	wear or breakage	replacing	every 6 months	if required

<sup>\*</sup> depending on the assessment of the distributor of the custom-made product regarding the patient's usage behaviour

<sup>\*\*</sup> is part of the functional unit

<sup>\*\*\*</sup> included system components can be exchanged separately