
patient commission/configuration ID \_\_\_\_\_





ltem	14mm	Description	Potential Problem	Measure	Recommended Inspection, Potential Replacement*	Latest Replacement after	
System Joint							
1	SK0892-1/C	bearing nut	wear	replacing	every 6 months	36 months	
3	GS2009-040	sliding washer, Ø = 20mm	wear	replacing	every 6 months	18 months	
3	GS2009-045						
3	GS2009-050						
3	GS2009-055						
3	GS2009-060						
4a	BP1009-L059	sliding bushing	wear	replacing	every 6 months	18 months	
6	SK9802-E005/C	5° extension stop	wear	replacing	every 6 months	if required	
9	SC1404-L10	countersunk flat head screw with hexalobular socket	wear	replacing	every 6 months	36 months	
System Anchors and System Side Bars							
10	see catalogue	system anchor and system side bar	wear or breakage	replacing	every 6 months	if required	
*	depending on the	sepending on the assessment of the distributor of the custom-made product regarding the patient's usage behaviour					

WP0121-GB-2023-01

